| Begin 2020 revision record. PC100 Revision History | | | | | | |
|--|--|--|--|-----|-------|------------|
| | | | | | | |
| PC100 | | | Revision Description | TB# | ECN# | Date |
| A1.00 | | | Prototype | | | |
| A1.02 | | | Redesigned dust chute bracket. | | 38960 | 4/21/2023 |
| A1.02 | | | Released to production. | | 39115 | 10/11/2023 |
| A2.00 | | | Move the access panel limit switches away from the panel fasteners, and replace the 1/4-20 Weld Nuts (F05010-40) with 1/4-20x1/2 Bosses (021258). Replace 116567 with 121136 in the left and right hand cabinet assemblies. So the limit switches are tripped by the access panels and not the fasteners. The weld nuts are stripping after multiple uses. 121136 is what is currently used in production. | | 39759 | 6/1/2025 |
| | | | | | | |
| | | | | | | |
| | | | | | | |