Book				
2426 Operation, Parts]	Machines Effected: LX25	TB#	ECN#	Date
A1.00	Part number [GDS and book] LX25G9 LX25G7		37321	4/20
	Revision Description Released LX25 to production			
A1.01	Part number [GDS and book] LX25G9 LX25G7		37562	8/20
	Revision Description Several variables including muffler orientation on engine, bend tolerances, and welding procedure when added up can result in the engine muffler interfering with the horizontal tube when sawhead is at max cut height. Changing to a bent channel allows for more clearance near the engine muffler while reducing manufacturing costs.			
A1.01	ECN's:		ECN:	25/05/2
	-37927: Replace M6 flat washer (F05026-1) with 1/4" flat washer (F05011-11); Comparing book to the GDS only in Watter Tank this washer was replaced. -37801: Add exhaust deflector, PN 110187, to power option assemblies, PNs G7 & G9.		- 37927 - 37801 - 37523 - 37805	
	- 37523: Enlarge holes used for door latch from 4mm to 5mm. Replace 4mm fasterners with 5mm.;F05027-8 replaced by F05027-3; F05020-27 replaced by F05020-38; Items Affected: M100/LX25 pan cover (X100-317) and cover assy (X100-967) - 37805: Correct CSI9 BOM to use the S31027 key in place of the S04124 key (G7 engines only).			
A1.02	Water Tank Assembly, 130983, replaced X100-970 due to supply issues for tank X100-904. New tank, 049119, and parts replaced previous assembly.		38414	02/23/2
A1.03	Change from 130983 water bottle assembly <i>back to</i> X100-970 water bottle assembly.		38565	5/31/20
	Administrative change: Created a top level LX25 without an engine, which will make the LX25G7 and LX25G9 obsolete as soon as they sell off all existing stock.			

LX Sawmill Revision History