

Twin Vertical Saw (TVS) Control Box Revision History (U.S. Only)

Rev	Revision Description	TB #	ECN #	Date
A7.00	New laser assembly.	---	18664	2/11
A8.00	Blade tensioner assembly replaced with the hydraulic blade tensioner (504826) equipped with the pump assembly.	110018PL	---	6/11
A9.00	Revised PLC Networks to be able to work with EG300: 069851-2 Setworks Control Assembly replaced 069851 including 069849 and 069850 used only on TVS prior to Rev. A9.00	---	---	11/13
B1.00	Changed terminal blocks from Schneider to Wago.	---	19919	5/14
B2.00	Changed PLC used in PLC Networks. Updated TVS control to DC control.	---	21134	9/16
B3.00	Converted controls to use Altivar 320 series AC drive rather than Altivar 312 series.	---	21477	7/17