

SLP Revision History

SLP Revision												Revision Description	TB #	ECN #	Date
TVS V Tables	HR500	HR1000 US Rev.	HR1000 PL Rev,	SVS	TVSFT	HR115	HR110	TVS-SC	SHS		HR700				
1001 1004	1006			1008 1009	1003 1005	924 925	926 927	1017 1018				Book & PDF Number			
A1.00	A1.00			A1.00								Introducing into production			
A2.00												Change the place where the calibration sensor is mounted Added the sawdust scraper on the feed chain tensioning wheel	080022pl 080024pl	4256 4259	6/08/2008 14/08/2008
A2.01	A1.01			A1.01								Blade Speed Reduction	090010pl	4470	11/05/2009
A2.02	A1.02			A1.02								New Blade Guide Rollers	090012pl	4469	08/06/2009
					A1.00							New product			
A3.00	A2.00			A2.00	A2.00							CE Electrical Connections Change		4810	14/12/2009
A4.00				A3.00								Blade Tensioner Complete		4816	12/01/2010
	A3.00											New Blade Drive Wheel & Bushing	100001pl	4468	15/02/2010
A4.01				A3.01	A2.01							Lasers change	100013pl	5008	03/2010 (red beam) 26/04/210 green beam)
A5.00												A new TVS 02 without calibration sensor.	100017pl	4997	17/05/2010
A5.01												The new TBS01 Setworks Controller (Part No. 503467)	100022pl	5160	03/08/2010
	A3.01											Feed Track Pads	100023pl	5203	23/08/2010
			A2.00									New Nomenclature		5023 5140	22/09/2010 02/08/2010
						A1.00	A1.00					New products			09/2010
A6.00					A3.00							New TVS Control Box	100032pl	5256	01/12/2010
								A1.00				New product			
						A1.00	A1.00					LT10 & LT15 and HR110 & HR115 Saw Head Unification (Blade Guide Tube)	#110007pl	#5512	18/03/2011
A7.00				A4.00	A4.00			A2.00				Hydraulic Blade Tensioner with blade brake pressure switch	#110018pl	#5466 #5596	30/05/2011
						A2.00	A2.00					New Blade Guide Roller Brackets	#110019pl	#5715	13/06/2011
			A3.00									New Drive Belt Tensioner		#5410	27.06.2011
			A4.00									New HydraulicTank Assembly		#5918	01.01.2012
							A2.01					Changed Saw Head in HR110		#5921	06.12.2011
									A1.00			Introduction into production			
								B1.00				New outfeed tables with side rollers.Certification		#5953 #6256	

TVS V Tables	HR500	HR1000 US Rev.	HR1000 PL Rev,	SVS	TVSFT	HR115	HR110	TVS-SC	SHS		HR700		#6061	31/10/2012
					B1.00									10/2012
					B1.00	A2.01							#6076	23/11/2012
		A2.01	A4.01										US #19342	12/11/2012
						A2.02							120022pl	#6076 14/12/2012
A7.02					B1.01								#6414	17/12/2012
A8.00				A5.00	B2.00			B2.00					#6182 #5972	28/02/2013
						A2.03	A2.02						#130004I	#6453 25/03/2013
				A6.00									#	#6407 18/03/2013
					B3.00			B3.00						
						A3.00	A3.00						#130009p I	#6626 #6641 26-06-2013
				A6.01									130013pl	#6972 12/11/2013
				A6.02									#7010	10/02/2014
A8.01													#7082	01/03/2014
	B1.00												140001pl	6634, 7116 03/03/2014
											A1.00			
A8.02				A6.03	B3.01	A3.01	A3.01	B3.01					#7220	02-06-2014
													#7416	
A8.03	B1.01			A6.04	B3.02			B3.02	A1.00		A1.01		#7754	16-01-2015
						A3.02	A3.02						#7876	25/02/2015
											A1.02		#8289	04/05/2015
				A6.05									7920	13/05/2015
					B3.03			B3.03					#8122	05/10/2015
											A1.03		#8403	
							A3.03						#7807	18/01/2016
	B2.00										A2.00		160008pl	#8393, #9710 06/2016