Begin 2010 revision record. (See also www.woodmizer.com/manuals/edger/twin blade/EG200rev.htm) **EG200 Revision History Model Revision** ED22 ED26 **EE15** EG25 EG26 (G28) ED24 (ED21) TB# ECN# **Revision Description** Date See HTML website file for prior revision history. (See www.woodmizer.com/manuals/edger/twin blade/EG200rev.htm) EG200EC15 EG200EG26 EG200ED26 EG200ED24 (G28) (ED21) A6.02 A6.02 A6.02 A6.02 Change to EG200 model number. ------7/10 A7.00 3/11 A7.00 A7.00 A7.00 --- (See rev. A8.00 changes: ECN 18699 re-issued with new revision) A7.01 A7.01 A7.01 18718 5/11 A7.01 Trailer light and mounting bracket replaced with LED light assemblies. ---A8.00 A8.00 A8.00 G29 power option replaces G28. 18699 6/11 6/12 A8.01 A8.01 A8.01 3TNV70-ASA3 Engine replaced 3TNV70-AMP Engine. Also, several parts were 19200 replaced (including stub shaft, bushing, flywheel housing, belt guard cover and harness assembly). Tail lights moved from side of edger to underneath to improve visability. 4/13 A8.02 A8.02 ---19471 A8.02 A8.03 Replaced gas tank with 076478 and gas tank tray with 076914 to meet new reg-20369 1/15 A8.03 A8.03 ulations. 20471 5/15 EG200G26 Only: Battery changed from P09725 to 028004 (5/15). Slide Assembly 074775 replaced Arbor Assembly 006447 (equipped with Blade 8/15 A9.00 A9.00 A9.00 20683 Retainer 038251 sold separately). 9/15 B1.00 B1.00 B1.00 Changed from P11813 motor to new 074780 motor. 20736 B2.00 B2.00 B2.00 Released new EPA/CARB compliant fuel container equipped with vapor return 20761 10/15 ---B2.01 B2.01 Diesel fuel containers permanently mounted to machines. New diesel containers 20848 12/15 B2.01 utilize same tray and cover already in production on gasoline models. EG200D24 equipped with 24HP Yanmar Tier4 Engine released to production ---20958 4/16 ------(replacing EG200D21 equipped with 21.5HP Yanmar Engine: 21.5HP engine no 20972 longer available). B2.02 B2.02 B2.02 Added fuel shut-off valve to 103878 gas can to prevent possibility of fuel feeding 21050 5/16 back into engine during travel. Created new service part 074943 Fuel Pick-Up With Shut-Off Fitting. B2.03 B2.03 B2.03 Change the supplied alternator to get better output at idle. Update guarding for 21226 11/16 the new alternator. **NOTE**: The supplied alternator on the D24 Yanmar engine was only giving around 3 amps of output at idle. This was not enough for the LT35 applications. Changed from internal to external slosh valve to prevent fuel from pushing B2.04 B2.04 B2.04 21344 2/17 --through the valve if tank is overfilled. Replaced 038160 Spacer Blocks with 079886 and 079887. Added slots to B2.05 B2.05 B2.05 21546 9/17 038068 Motor Plate. B2.06 B2.06 B2.06 Replaced motor 074780 with 130000 on the EG200 37390 4/20 B2.07 5/21 B2.07 B2.07 Rearranged the sub-assemblies -- no parts changes. 37934