Begin 2010 revision record. HR1000 Series Revision History				
HR1000	Revision Description	TB#	ECN#	Date
A1.01	Introduced new sawhead design and product nomenclature.		18269	5/10
A2.00	4HP hydraulic drive motor discontinued by vendor and replaced with 5HP motor. Perimeter fence limit switch replaced to reduce cost and dual-pistons added to 5/6-head models to improve perimeter fence function.		17463 18951	10/11
A2.01	Replaced pressure gauge with 1/4" NPT pipe plug in hydraulic flow control.		19342	11/12
A2.02	Introduced new 25HP electric motor with internal thermostats.		19646	10/13
A2.03	Added fingers inside sawdust chute to prevent operator contact with blade (CE requirement).		19920	2/14
A2.04	Introduced new industrial decals.		20307	12/14
A2.06	Change drive blade motor. Replace the 007723 drive belt with new belt 128300.		37651	9/20