

Wood-Mizer Spare Parts Pak

061125

Parts Pak, BMS500CU

<i>Part Number</i>	<i>Description</i>	<i>Quantity</i>
052446	Fuse, 2A 600V KLDR Class CC	2
069698	Fuse, 3A Class CC Fast-Acting	3
090452	SWITCH, M22 START/STOP	1
092208	Spring, 1.6x12x38 Extension	1
093358	PUSHER, BLADE COMPLETE	1
098513	Sprocket, 05B-1 Z20 8x3-12H7, Zinc PTD	3
098515	Chain, Blade Height Adj. -Complete	1
100804	Belt, 4PJ660 (OPTIBELT)	1
100816	Bearing, 6301-DDU (NSK) Rolling	2
101252	Sensor, SMC08S Magnetic	1
101253	Magnet, M20 Sensor	1
500039	Rectifier, W005M 1.5 50V Bridge	1
500464	Spring, 150N-Complete Gas Lifting	1
510283	Fuse, 5A Class CC Time Delay	3
A10617	Support Assy, Blade Replacement	1
E20519	Potentiometer, 1K LTAGA **OOP**	1
F81044-7	Pin, 4x30 Spring-Type Strait Zinc	3
P09836	Pump, Coolant (LTAGA) **OOP**	1